

SECRET

OUT56160

Declassification Review by NGA/DoD

S E C R E T 122134Z

1965 JUL 12 23 43Z

1
25X1

1. CAMERA B 7 WAS USED IN MISSION 8029 FLOWN ON 9 JULY 1965. PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: A ROW OF MINUS DENSITY DOTS 1.55" APART AND 2.1" FROM THE INBOARD EDGE IS PRESENT FROM FRAME 295 TO THE END OF THE MISSION. TWO FINE PLUS DENSITY LINES LOCATED 2.65" AND 4.1" FROM AND PARALLEL TO THE INBOARD EDGE OF THE FILM ARE PRESENT INTERMITTENTLY THROUGHOUT THE MISSION. WAVERING STREAKS OF PLUS DENSITY LOCATED WITHIN 2.0" OF THE INBOARD EDGE OCCUR AT RANDOM THROUGHOUT THE MISSION. HEAT SPLICES ARE LOCATED BETWEEN FRAMES 1203/1204, 1244/1245 AND IN FRAME 900. A MANUFACTURER'S SPLICE IS PRESENT IN FRAME 1699.

C. 9L SIDE: IRREGULAR PLUS DENSITY STREAKS OCCUR INTERMITTENTLY NEAR THE INBOARD EDGE OF THE FILM ON FRAMES 851 TO 854; 1194 TO 1198; 1219/1220; 1508 TO 1517; 1539/1540; AND 1594 TO 1619. PLUS DENSITY STREAKS, PARALLEL TO THE FILM'S EDGES, ARE PRESENT INTERMITTENTLY THROUGHOUT THIS SIDE. THE FOLLOWING LIST GIVES THE LOCATION OF THESE PLUS DENSITY STREAKS:

- (1) 2.7" FROM THE OUTBOARD EDGE ON FRAMES 250 TO 712.
- (2) 5.35" FROM THE OUTBOARD EDGE ON FRAMES 250 TO 823.
- (3) 2.23" FROM THE INBOARD EDGE ON FRAMES 823 TO 840.

13 JUL 1965

COPIES RECEIVED		
Cy No.	Office	Act.
1	Ent	
	OS	
	ADMIN	
	SEC BR	
	P&DS	
	CSD	
	IPD	
	PD	
	PSD	
	PSD-ICB	
3,4	TID	
	PID	
	PAG	
	DIAXX	
	SPAD	
	NSA-IO	
	DIA-AP	

SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification

25X1

(4) 1.7" FROM THE OUTBOARD EDGE ON FRAMES 851 TO 1800.

(5) 2.3" FROM THE OUTBOARD EDGE ON FRAMES 851 TO 1449.

(6) 2.28" FROM THE INBOARD EDGE ON FRAMES 1166 TO 1800.

A MANUFACTURER'S SPLICE IS PRESENT IN FRAME 166 WITH ASSOCIATED FOG AND MINOR CRIMPS. HEAT SPLICES ARE PRESENT BETWEEN FRAMES 245/246 AND 786/787 AND IN FRAME 841.

D. BOTH SIDES: THE VERTICAL INDICATOR DOT IS BLOOMED AND THE 1R AND 2L POSITION INDICATORS ARE FAINT ON BOTH SIDES. EDGE STATIC/FOG IS PRESENT ALONG BOTH EDGES OF EACH SIDE OF THE MISSION. ROLLER CHATTER (PRESSURE ROLLER STATIC) IS LOCATED NEAR THE INBOARD EDGE OF BOTH SIDES THROUGHOUT THE MISSION. THE LAST TITLED FRAME ON EACH SIDE IS 1800.

E. THERE WERE NO MAJOR PROCESSING ANOMALIES OR CAMERA MALFUNCTIONS IN THIS MISSION.

3. POSITIVE:

A. PI SUITABILITY IS GOOD.

B. PRINTING AND PROCESSING WERE GOOD.

C. CLOUDS DEGRADE OR OBSCURE APPROXIMATELY 15 PERCENT OF THE MISSION.

S E C R E T

/END OF MESSAGE/